TYX CORPORATION

Productivity Enhancement Systems

PAWS Studio
Release Notes

Version 1.37.16
December 17, 2009

Table of contents

1   Paws Developer's Studio

Version 1.37.16
Release date: December 17, 2009

1.1   Critical Items

1.2   Known Limitations

1.3   Enhancements

1.3.1   1641 CLCEx.exe Carrier Language Compiler enhanced

This version of 1641CLCEx.exe has the SIGNAL-ID modifiers printed before the rest of the signal modifiers. This feature has been required by the EADS-TS UK. It also fixes a translating error that consisted of having double end-of-string markers present in the atlas code each time constant strings were involved.

1.4   Problem Reports

2   Run Time System

Version 1.37.16
Release date: December 17, 2009

2.1   Critical Items

2.2   Known Limitations

2.3   Enhancements

2.4   Problem Reports